

FIG. 1




FIG. 2

70




FIG. 3




FIG. 5



Circuit Technology Center, Inc.

SMTnet.com : Company Mini-Page

Company Type: Consultant/Service Provider



[Email This Page to a Friend](#)



[Printer Friendly Version](#)



[See it on a Map](#)

Summary:

Largest US company providing services to repair and rework assembled or bare circuit boards, sells wide selection of production tools and supplies, offers training courses in soldering, rework and repair. Facilities in Massachusetts and California.

List of Major Services:

Services	Description
circuit board repair	Repair of pads, conductors, base board.
circuit board rework	Removal\replacement of SMT through hole components.
BGA repair\rework	Removal\replacement of BGA components, repair of BGA pads.
Circuit board modification	Adding jumper wires, cuts, etc..

Offices:

Main Office

45 Research Drive
Haverhill , Massachusetts 01832-1293
United States of America
Tel: 978-374-5000
Fax: 978-372-5700
Email: info@circuitnet.com
Web: <http://www.circuitnet.com>

[⬆ Back to Top](#)

Send questions or comments to info@smtnet.com © 1995-2000 SMTnet

FIG. 4




- 100
- ★ SMT - Cpk for Attribute Data - C D oley 16:12:01 12/13/2000  V.I. Technologies Forum
 - Re: SMT - Cpk for Attribute Data - Dave F 20:46:46 12/13/2000
 - ★ Reflow Profile Dry Out Stage - Chris 14:15:54 12/13/2000
 - Re: Reflow Profile Dry Out Stage - Steve A 18:41:33 12/13/2000
 - Re: Reflow Profile Dry Out Stage - Chris 14:37:06 12/13/2000
 - Re: Reflow Profile Dry Out Stage - Michael Parker 16:47:41 12/13/2000
 - ★ PCB laminate dielectric absorption - Mike Ihm 13:42:57 12/13/2000
 - Re: PCB laminate dielectric absorption - Dave F 20:42:57 12/13/2000
 - ★ Desperately looking for help - George 10:11:36 12/13/2000  Circuit Technology Center
 - Re: Desperately looking for help - Dave F 20:39:04 12/13/2000
 - Re: Desperately looking for help - Wolfgang Busko 11:24:10 12/13/2000
 - Re: Desperately looking for help - Travis Slaughter 11:15:20 12/13/2000
 - Re: Desperately looking for help - CAL 11:11:20 12/13/2000
 - Re: Desperately looking for help - George 08:29:18 12/14/2000  Circuit Technology Center
 - ★ silver finishes on pcbs - jacqueline 09:42:44 12/13/2000
 - Re: silver finishes on pcbs - PeteB 10:14:04 12/14/2000
 - Re: silver finishes on pcbs - Dave F 20:30:59 12/13/2000
 - Re: silver finishes on pcbs - what about the wave? - JohnW 03:35:10 12/15/2000
 - Re: silver finishes on pcbs - what about the wave? - Pete B 08:00:57 12/15/2000
 - Re: silver finishes on pcbs - Wolfgang Busko 10:24:52 12/13/2000
 - ★ Work permit for US - narasimhan68 20:37:31 12/12/2000
 - ★ Work permit for US - narasimhan68 20:37:13 12/12/2000
 - Re: Work permit for US - Dave F 20:51:45 12/12/2000
 - ★ Feeder tape splice jams - Chris Newell 14:47:55 12/12/2000
 - Re: Feeder tape splice jams - Stefan Witte 12:08:57 12/13/2000
 - Re: Feeder tape splice jams - CAL 08:28:37 12/13/2000
 - Re: Feeder tape splice jams - G. English 03:40:13 12/13/2000
 - ▼ difficult posting - Wolfgang Busko 09:42:10 12/12/2000
 - Re: difficult posting - Neil Peaslee 13:45:22 12/12/2000
 - ★ Dross Removal - Chris Bettlejewski 07:01:45 12/12/2000
 - Re: Dross Removal - justin medernach 13:33:52 12/12/2000
 - what I meant to say was.... - justin m 13:45:23 12/12/2000
 - ★ solder balls on high temp.solder - accuspec 15:12:20 12/11/2000
 - Re: solder balls on high temp.solder - Jerry Wetzel, SME, EM/SME 19:40:38 12/13/2000
 - Re: solder balls on high temp.solder - ralph 17:54:04 12/12/2000
 - Re: solder balls on high temp.solder - Chris May 03:15:13 12/12/2000
 - Re: solder balls on high temp.solder - Michael Parker 17:09:27 12/11/2000
 - Re: solder balls on high temp.solder - externet 15:50:01

FIG. 6